

**Flood Control Project Maintenance  
Levee Inspections**

**2011 Channel Summary Report**

**Overall Unit and Item Ratings**

**Fairfield Suisun Sewer District**

**Laurel Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Ledgewood Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Gates	U *

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**McCoy Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Union Avenue Diversion**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance****Unit Cover Sheet****2011 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Laurel Creek

Channel Rating	<b>M</b>
Date of Inspection	8/2/2011 - 8/3/2011
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Cement Hill Rd	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.279793 ° -122.018267 °	Y	1
2		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.279793 ° -122.018267 °		2
3		Up	Erosion / Bank Caving		A		38.279793 ° -122.018267 °		3
4		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.279793 ° -122.018267 °		4
5		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.279793 ° -122.018267 °		5
6		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.279793 ° -122.018267 °	Y	6
7		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.279793 ° -122.018267 °		7
8		Down	Erosion / Bank Caving		A		38.279793 ° -122.018267 °		8
9		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.279793 ° -122.018267 °		9
10		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.279793 ° -122.018267 °		10
11	Air Base Parkway	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.272625 ° -122.015993 °	Y	11
12		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.272625 ° -122.015993 °		12
13		Up	Erosion / Bank Caving		A		38.272625 ° -122.015993 °		13
14		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.272625 ° -122.015993 °		14

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
15		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.272625 ° -122.015993 °		15
16		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.272625 ° -122.015993 °	Y	16
17		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.272625 ° -122.015993 °		17
18		Down	Erosion / Bank Caving		A		38.272625 ° -122.015993 °		18
19		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.272625 ° -122.015993 °		19
20		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.272625 ° -122.015993 °		20
21	Meadowlark Dr	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.268240 ° -122.017115 °	Y	21
22		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.268240 ° -122.017115 °		22
23		Up	Erosion / Bank Caving		A		38.268240 ° -122.017115 °		23
24		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.268240 ° -122.017115 °		24
25		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.268240 ° -122.017115 °		25
26		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.268240 ° -122.017115 °	Y	26
27		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.268240 ° -122.017115 °		27
28		Down	Erosion / Bank Caving		A		38.268240 ° -122.017115 °		28

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
29		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.268240 ° -122.017115 °		29
30		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.268240 ° -122.017115 °		30
31	East Tabor Ave	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.265262 ° -122.018443 °	Y	31
32		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.265262 ° -122.018443 °		32
33		Up	Erosion / Bank Caving		A		38.265262 ° -122.018443 °		33
34		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.265262 ° -122.018443 °		34
35		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.265262 ° -122.018443 °		35
36		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.265262 ° -122.018443 °	Y	36
37		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.265262 ° -122.018443 °		37
38		Down	Erosion / Bank Caving		A		38.265262 ° -122.018443 °		38
39		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.265262 ° -122.018443 °		39
40		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.265262 ° -122.018443 °		40
41	Matthew Rd	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.259272 ° -122.017533 °	Y	41

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
42		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.259272 ° -122.017533 °		42
43		Up	Erosion / Bank Caving		A		38.259272 ° -122.017533 °		43
44		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.259272 ° -122.017533 °		44
45		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.259272 ° -122.017533 °		45
46		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.259272 ° -122.017533 °	Y	46
47		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.259272 ° -122.017533 °		47
48		Down	Erosion / Bank Caving		A		38.259272 ° -122.017533 °		48
49		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.259272 ° -122.017533 °		49
50		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.259272 ° -122.017533 °		50
51	Railroad Ave	Up	Vegetation & Obstructions		N	Inspector Comments: This item does not apply to this inspection.	38.257752 ° -122.017769 °		51
52		Up	Shoaling / Sedimentation		N	Inspector Comments: This item does not apply to this inspection.	38.257752 ° -122.017769 °		52
53		Up	Erosion / Bank Caving		N	Inspector Comments: This item does not apply to this inspection.	38.257752 ° -122.017769 °		53
54		Up	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.257752 ° -122.017769 °		54

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
55		Up	Encroachments		N	Inspector Comments: This item does not apply to this inspection.	38.257752 ° -122.017769 °		55
56		Down	Vegetation & Obstructions		M	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.	38.257752 ° -122.017769 °	Y	56
57		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.257752 ° -122.017769 °		57
58		Down	Erosion / Bank Caving		A		38.257752 ° -122.017769 °		58
59		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.257752 ° -122.017769 °		59
60		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.257752 ° -122.017769 °		60
61	SunsetAve	Up	Vegetation & Obstructions		U	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253409 ° -122.020114 °	Y	61
62		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.253409 ° -122.020114 °		62
63		Up	Erosion / Bank Caving		A		38.253409 ° -122.020114 °		63
64		Up	Revetments		M	Inspector Comments: No riprap displacement or scouring activity. Unwanted vegetation must be cleared and sprayed with an appropriate herbicide.	38.253409 ° -122.020114 °		64
65		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253409 ° -122.020114 °		65
66		Down	Vegetation & Obstructions		U	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253409 ° -122.020114 °	Y	66
67		Down	Shoaling / Sedimentation		A		38.253409 ° -122.020114 °		67

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel				Channel Length	Inspection Start/End	Inspector
Laurel Creek				2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
68		Down	Erosion / Bank Caving		A		38.253409 ° -122.020114 °		68
69		Down	Revetments		M	Inspector Comments: No riprap displacement or scouring activity. Unwanted vegetation must be cleared and sprayed with an appropriate herbicide.	38.253409 ° -122.020114 °		69
70		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253409 ° -122.020114 °		70
71	Blossom Rd	Up	Vegetation & Obstructions		U	Inspector Comments: Snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253382 ° -122.014862 °	Y	71
72		Up	Shoaling / Sedimentation		A		38.253382 ° -122.014862 °		72
73		Up	Erosion / Bank Caving		A		38.253382 ° -122.014862 °		73
74		Up	Revetments		M	Inspector Comments: No riprap displacement or scouring activity. Unwanted vegetation must be cleared and sprayed with an appropriate herbicide.	38.253382 ° -122.014862 °		74
75		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253382 ° -122.014862 °		75
76		Down	Vegetation & Obstructions		U	Inspector Comments: Snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253382 ° -122.014862 °	Y	76
77		Down	Shoaling / Sedimentation		A		38.253382 ° -122.014862 °		77
78		Down	Erosion / Bank Caving		A		38.253382 ° -122.014862 °		78
79		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.253382 ° -122.014862 °		79

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Laurel Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
80		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253382 ° -122.014862 °		80
81	Worley Rd	Up	Vegetation & Obstructions		U	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253248 ° -122.009732 °	Y	81
82		Up	Shoaling / Sedimentation		A		38.253248 ° -122.009732 °		82
83		Up	Erosion / Bank Caving		A		38.253248 ° -122.009732 °		83
84		Up	Revetments		A		38.253248 ° -122.009732 °		84
85		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253248 ° -122.009732 °		85
86		Down	Vegetation & Obstructions		U	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253248 ° -122.009732 °	Y	86
87		Down	Shoaling / Sedimentation		A		38.253248 ° -122.009732 °		87
88		Down	Erosion / Bank Caving		A		38.253248 ° -122.009732 °		88
89		Down	Revetments		A		38.253248 ° -122.009732 °		89
90		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253248 ° -122.009732 °		90

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

This is the downstream view of Laurel Creek at Manuel Campos Pkwy. 38.29300 -122.02265

johngw\_c\_20110804\_017.jpg



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

This is the upstream view of Laurel Creek at Manuel Campos Pkwy.

johngw\_c\_20110804\_018.jpg



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

This view is looking downstream of Laurel Creek at Dickson Hill Rd. The trees need to be raised so not to impede flow. 38.28982 -122.02077

johngw\_c\_20110804\_019.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

This is another view of the upstream of Laurel Creek at Manual Campos Pkwy. The trees need to be raised so not to impede flow.

johngw\_c\_20110804\_020.jpg



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

This view is the upstream view of Laurel Creek at Dickson Hill Rd. The trees need to be raised so not to impede flow.

johngw\_c\_20110804\_021.jpg



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream from Cement Hill Rd.

johngw\_c\_20110804\_022.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Cement Hill Rd.

johngw\_c\_20110804\_023.jpg



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Air Base Pkwy.

johngw\_c\_20110804\_024.jpg



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Air Base Pkwy. The bridge in the photo is Nightingale.

johngw\_c\_20110804\_025.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Nightingale.

johngw\_c\_20110804\_026.jpg



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Meadowlark Dr.

johngw\_c\_20110804\_027.jpg



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Meadowlark Dr.

johngw\_c\_20110804\_028.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

the photo is looking upstream at E. Tabor Ave.

johngw\_c\_20110804\_029.jpg



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at E. Tabor ave.

johngw\_c\_20110804\_030.jpg



Levee Mile Report Line	41
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Matthew Dr.

johngw\_c\_20110804\_031.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Matthew Dr. The five pipes run under the railroad tracks. This is the end for the city of Fairfield on Laurel Creek.

johngw\_c\_20110804\_032.jpg



Levee Mile Report Line	56
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Railroad Ave. Trees are growing in the channel. The city of Suisun takes over Laurel Creek.

johngw\_c\_20110804\_033.jpg



Levee Mile Report Line	61
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Sunset Ave and Railroad Ave. Trees and brush need to be sprayed or cut out.

johngw\_c\_20110804\_034.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	66
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Sunset Ave.

johngw\_c\_20110804\_035.jpg



Levee Mile Report Line	71
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Blossom Rd.

johngw\_c\_20110804\_036.jpg



Levee Mile Report Line	71
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The debris is dead cattails that has collected at the bridge and creates some blockage.

johngw\_c\_20110804\_037.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Laurel Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	76
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Blossom Rd.

johngw\_c\_20110804\_038.jpg



Levee Mile Report Line	81
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Worley Rd. Cattails are encroaching into the bridge and could create blockage.

johngw\_c\_20110804\_039.jpg



Levee Mile Report Line	86
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Worley Rd. Willows and other trees are growing in the channel.

johngw\_c\_20110804\_040.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance****Unit Cover Sheet****2011 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Ledgewood Creek

Channel Rating	<b>M *</b>
Date of Inspection	8/2/2011 - 8/3/2011
DWR Inspector	John Williamson
Accompanied By	

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel					Channel Length	Inspection Start/End	Inspector
Ledgewood Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Astoria Drive	Up	Vegetation & Obstructions		A		38.256147 ° -122.073892 °	Y	1
2		Up	Shoaling / Sedimentation		A		38.256147 ° -122.073892 °		2
3		Up	Erosion / Bank Caving		A		38.256147 ° -122.073892 °		3
4		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.256147 ° -122.073892 °		4
5		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.256147 ° -122.073892 °		5
6		Down	Vegetation & Obstructions		A		38.256147 ° -122.073892 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.256147 ° -122.073892 °		7
8		Down	Erosion / Bank Caving		A		38.256147 ° -122.073892 °		8
9		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.256147 ° -122.073892 °		9
10		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.256147 ° -122.073892 °		10
11	Springfield Dr.	Up	Vegetation & Obstructions		A		38.254582 ° -122.073597 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.254582 ° -122.073597 °		12
13		Up	Erosion / Bank Caving		A		38.254582 ° -122.073597 °		13
14		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.254582 ° -122.073597 °		14

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Ledgewood Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
15		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.254582 ° -122.073597 °		15
16		Down	Vegetation & Obstructions		A		38.254582 ° -122.073597 °	Y	16
17		Down	Shoaling / Sedimentation		A		38.254582 ° -122.073597 °		17
18		Down	Erosion / Bank Caving		A		38.254582 ° -122.073597 °		18
19		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.254582 ° -122.073597 °		19
20		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.254582 ° -122.073597 °		20
21	Rockville Road	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.249960 ° -122.072670 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.249960 ° -122.072670 °		22
23		Up	Erosion / Bank Caving		A		38.249960 ° -122.072670 °		23
24		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.249960 ° -122.072670 °		25
25		Up	Gates		U	Inspector Comments: Gate is missing, has been damaged or has deteriorated and needs repair.	38.249960 ° -122.072670 °	Y	24
26		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.249960 ° -122.072670 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.249960 ° -122.072670 °		27
28		Down	Erosion / Bank Caving		A		38.249960 ° -122.072670 °		28

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Ledgewood Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
29		Down	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.249960 ° -122.072670 °		29
30		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.249960 ° -122.072670 °		30
31	Auto Mall Parkway	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.247722 ° -122.072105 °	Y	31
32		Up	Shoaling / Sedimentation		A		38.247722 ° -122.072105 °		32
33		Up	Erosion / Bank Caving		A		38.247722 ° -122.072105 °		33
34		Up	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.247722 ° -122.072105 °		34
35		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.247722 ° -122.072105 °		35
36		Down	Vegetation & Obstructions		A		38.247722 ° -122.072105 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.247722 ° -122.072105 °		37
38		Down	Erosion / Bank Caving		A		38.247722 ° -122.072105 °		38
39		Down	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.247722 ° -122.072105 °		39
40		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.247722 ° -122.072105 °		40
41	Woolner Avenue	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.242275 ° -122.070478 °	Y	41
42		Up	Shoaling / Sedimentation		A		38.242275 ° -122.070478 °		42

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Ledge Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
43		Up	Erosion / Bank Caving		A		38.242275 ° -122.070478 °		43
44		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.242275 ° -122.070478 °		44
45		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.242275 ° -122.070478 °		45
46		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.242275 ° -122.070478 °	Y	46
47		Down	Shoaling / Sedimentation		A		38.242275 ° -122.070478 °		47
48		Down	Erosion / Bank Caving		A		38.242275 ° -122.070478 °		48
49		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.242275 ° -122.070478 °		49
50		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.242275 ° -122.070478 °		50
51	Beck Avenue	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.243702 ° -122.066538 °	Y	51
52		Up	Shoaling / Sedimentation		A		38.243702 ° -122.066538 °		52
53		Up	Erosion / Bank Caving		A		38.243702 ° -122.066538 °		53
54		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.243702 ° -122.066538 °		54
55		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area. Encroachments which do not diminish proper functioning of the project have been previously approved by the Rec. Board.	38.243702 ° -122.066538 °		55

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
56		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.243702 ° -122.066538 °	Y	56
57		Down	Shoaling / Sedimentation		A		38.243702 ° -122.066538 °		57
58		Down	Erosion / Bank Caving		A		38.243702 ° -122.066538 °		58
59		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.243702 ° -122.066538 °		59
60		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area. Encroachments which do not diminish proper functioning of the project have been previously approved by the Rec. Board.	38.243702 ° -122.066538 °		60
61	Highway 12	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.240590 ° -122.062413 °	Y	61
62		Up	Shoaling / Sedimentation		A		38.240590 ° -122.062413 °		62
63		Up	Erosion / Bank Caving		A		38.240590 ° -122.062413 °		63
64		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.240590 ° -122.062413 °		64
65		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.240590 ° -122.062413 °		65
66		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.240590 ° -122.062413 °	Y	66
67		Down	Shoaling / Sedimentation		A		38.240590 ° -122.062413 °		67
68		Down	Erosion / Bank Caving		A		38.240590 ° -122.062413 °		68

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Ledgewood Creek					2.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
69		Down	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.240590 ° -122.062413 °		69
70		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.240590 ° -122.062413 °		70
71	Cordelia Road	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.233310 ° -122.058590 °	Y	71
72		Up	Shoaling / Sedimentation		A		38.233310 ° -122.058590 °		72
73		Up	Erosion / Bank Caving		A		38.233310 ° -122.058590 °		73
74		Up	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.233310 ° -122.058590 °		74
75		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.233310 ° -122.058590 °		75
76		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.233310 ° -122.058590 °	Y	76
77		Down	Shoaling / Sedimentation		A		38.233310 ° -122.058590 °		77
78		Down	Erosion / Bank Caving		A		38.233310 ° -122.058590 °		78
79		Down	Revetments		N	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.233310 ° -122.058590 °		79
80		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.233310 ° -122.058590 °		80

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
The photo is looking at the inlet from the retention basin to Ledgewood Creek.	
johngw_c_20110804_049.jpg	



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
the photo is looking downstream and the outlet from the retention basin. It is located behind 1411 Oliver Rd.	
johngw_c_20110804_050.jpg	



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
The photo is looking upstream at Astoria Dr.	
johngw_c_20110804_051.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Astoria Dr.

johngw\_c\_20110804\_052.jpg



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Springfield Dr.

johngw\_c\_20110804\_053.jpg



Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Springfield Dr.

johngw\_c\_20110804\_054.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Rockville Rd.

johngw\_c\_20110804\_055.jpg



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The flap gate is broken off and needs to be replaced.

johngw\_c\_20110804\_056.jpg



Levee Mile Report Line	25
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Gates

The flap gate on the up stream side is missing and needs to be replaced.

johngw\_c\_20110810\_071.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Rockville Rd. Need to keep trees trimmed up.

johngw\_c\_20110804\_057.jpg



Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Auto Mall Pkw.

johngw\_c\_20110804\_058.jpg



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Auto Mall Pkw.

johngw\_c\_20110804\_059.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The bridge is being widen this the footing on the left bank.

johngw\_c\_20110804\_060.jpg



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is the footing on the right bank.

johngw\_c\_20110804\_061.jpg



Levee Mile Report Line	41
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Woolner Ave.

johngw\_c\_20110804\_062.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	46
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Woolner Ave.

johngw\_c\_20110804\_063.jpg



Levee Mile Report Line	51
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Beck Ave. The work is for permit 18591.

johngw\_c\_20110804\_064.jpg



Levee Mile Report Line	56
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Beck Ave.

johngw\_c\_20110804\_065.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	61
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The view is looking upstream at Highway 12.

johngw\_c\_20110804\_066.jpg



Levee Mile Report Line	66
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Highway 12.  
The trees need to be raised.

johngw\_c\_20110804\_067.jpg



Levee Mile Report Line	66
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The trees need to be trimmed up to 5 ft.

johngw\_c\_20110804\_068.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Ledgewood Creek	2.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	71
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Cordelia Rd.  
The cattails need to be sprayed or removed at least 50 ft.

johngw\_c\_20110804\_069.jpg



Levee Mile Report Line	76
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Cordelia Rd.  
The cattails need to be sprayed or removed at least 50 ft.

johngw\_c\_20110804\_070.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance****Unit Cover Sheet**  
**2011 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
McCoy Creek

Channel Rating	<b>M</b>
Date of Inspection	8/2/2011 - 8/3/2011
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
McCoy Creek					1.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Bella Vista Dr	Up	Vegetation & Obstructions		M	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.	38.253280 ° -122.000670 °	Y	1
2		Up	Shoaling / Sedimentation		A		38.253280 ° -122.000670 °		2
3		Up	Erosion / Bank Caving		A		38.253280 ° -122.000670 °		3
4		Up	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.253280 ° -122.000670 °		4
5		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253280 ° -122.000670 °		5
6		Down	Vegetation & Obstructions		U	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 50% of the FCW.	38.253280 ° -122.000670 °	Y	6
7		Down	Shoaling / Sedimentation		A		38.253280 ° -122.000670 °		7
8		Down	Erosion / Bank Caving		A		38.253280 ° -122.000670 °		8
9		Down	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.253280 ° -122.000670 °		9
10		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.253280 ° -122.000670 °		10
11	Emperor Dr	Up	Vegetation & Obstructions		A	Inspector Comments: Cattails need to be sprayed or removed at street crossing.	38.250738 ° -122.004355 °	Y	11
12		Up	Shoaling / Sedimentation		A		38.250738 ° -122.004355 °		12
13		Up	Erosion / Bank Caving		A		38.250738 ° -122.004355 °		13

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
McCoy Creek					1.00	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
14		Up	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.250738 ° -122.004355 °		14
15		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.250738 ° -122.004355 °		15
16		Down	Vegetation & Obstructions		A	Inspector Comments: Cattails need to be sprayed or removed at street crossing. Try to maintain 50 ft. to 100 ft. clearance.	38.250738 ° -122.004355 °	Y	16
17		Down	Shoaling / Sedimentation		A		38.250738 ° -122.004355 °		17
18		Down	Erosion / Bank Caving		A		38.250738 ° -122.004355 °		18
19		Down	Revetments		N	Inspector Comments: This item does not apply to this inspection.	38.250738 ° -122.004355 °		19
20		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.250738 ° -122.004355 °		20
21	Pintail Ave	Up	Vegetation & Obstructions		M	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW. There is a dam formed by a beaver or debris.	38.248542 ° -122.006378 °	Y	21
22		Up	Shoaling / Sedimentation		A		38.248542 ° -122.006378 °		22
23		Up	Erosion / Bank Caving		A		38.248542 ° -122.006378 °		23
24		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.248542 ° -122.006378 °		24
25		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.248542 ° -122.006378 °		25

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/02/2011 08/03/2011	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
26		Down	Vegetation & Obstructions		M	Inspector Comments: Log jams, snags, vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.	38.248542 ° -122.006378 °	Y	26
27		Down	Shoaling / Sedimentation		A		38.248542 ° -122.006378 °		27
28		Down	Erosion / Bank Caving		A		38.248542 ° -122.006378 °		28
29		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.248542 ° -122.006378 °		29
30		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.248542 ° -122.006378 °		30
31	Anderson Dr	Up	Vegetation & Obstructions		M	Inspector Comments: Vegetation growth (such as cat tails, bull rushes, bushes or saplings) or other obstructions block approximately 25% of the FCW.	38.241288 ° -122.012057 °		31
32		Up	Shoaling / Sedimentation		A		38.241288 ° -122.012057 °		32
33		Up	Erosion / Bank Caving		A		38.241288 ° -122.012057 °		33
34		Up	Revetments		A		38.241288 ° -122.012057 °		34
35		Up	Encroachments		A		38.241288 ° -122.012057 °		35
36		Down	Vegetation & Obstructions		A	Inspector Comments: Cattails should be sprayed or cleared 50 ft. to 100 ft. from road crossing.	38.241288 ° -122.012057 °	Y	36
37		Down	Shoaling / Sedimentation		A		38.241288 ° -122.012057 °		37
38		Down	Erosion / Bank Caving		A		38.241288 ° -122.012057 °		38
39		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.241288 ° -122.012057 °		39

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/02/2011 08/03/2011	John Williamson

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
40		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.241288 ° -122.012057 °		40

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
<p>The photo is looking upstream at Bella Vista Dr. The flashboard structure is completely obstructed by cattails and could not function.</p> <p>johngw_c_20110804_041.jpg</p>	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
<p>The photo is looking downstream at Bella Vista Dr.</p> <p>johngw_c_20110804_042.jpg</p>	



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions
<p>The photo is looking upstream at Emperor Dr.</p> <p>johngw_c_20110804_043.jpg</p>	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Emperor Dr.

johngw\_c\_20110804\_044.jpg



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Pintail Ave. The cattails need to be sprayed are removed at the bridge. There is a small beaver dam in the channel.

johngw\_c\_20110804\_045.jpg



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Pintail Ave.

johngw\_c\_20110804\_046.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

## Channel Inspection Report By Check Point and View Direction - 2011

### Fairfield Suisun Sewer District

Channel	Channel Length	Inspection Start/End	Inspector
McCoy Creek	1.00	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Highway 12 bike trail. The cattails need to be sprayed are removed at the bridge at least 50 ft.

johngw\_c\_20110804\_047.jpg



Levee Mile Report Line	36
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream at Anderson Dr. The cattails need to be sprayed are removed at least 50 ft.

johngw\_c\_20110804\_048.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance****Unit Cover Sheet****2011 Channel Inspection Results****Fairfield Suisun Sewer District**

Channel
Union Avenue Diversion

Channel Rating	<b>A</b>
Date of Inspection	8/2/2011 - 8/3/2011
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/02/2011 08/03/2011	John Williamson

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	N. Texas St	Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.280582 ° -122.033912 °	Y	6
2		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.280582 ° -122.033912 °		7
3		Down	Erosion / Bank Caving		A	Inspector Comments: No head cutting or horizontal deviation observed.	38.280582 ° -122.033912 °		8
4		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.280582 ° -122.033912 °		9
5		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.280582 ° -122.033912 °		10
6	Camrose Ave	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.281668 ° -122.030495 °	Y	11
7		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.281668 ° -122.030495 °		12
8		Up	Erosion / Bank Caving		A		38.281668 ° -122.030495 °		13
9		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.281668 ° -122.030495 °		14
10		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.281668 ° -122.030495 °		15
11		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.281668 ° -122.030495 °	Y	16
12		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.281668 ° -122.030495 °		17
13		Down	Erosion / Bank Caving		A		38.281668 ° -122.030495 °		18
14		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.281668 ° -122.030495 °		19

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion					0.75	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location	Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
15		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.281668 ° -122.030495 °		20
16	Dover Ave	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.280990 ° -122.024750 °	Y	21
17		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.280990 ° -122.024750 °		22
18		Up	Erosion / Bank Caving		A		38.280990 ° -122.024750 °		23
19		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.280990 ° -122.024750 °		24
20		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.280990 ° -122.024750 °		25
21		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.280990 ° -122.024750 °	Y	26
22		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.280990 ° -122.024750 °		27
23		Down	Erosion / Bank Caving		A		38.280990 ° -122.024750 °		28
24		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.280990 ° -122.024750 °		29
25		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.280990 ° -122.024750 °		30
26	Gulf Dr	Up	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.281002 ° -122.020570 °	Y	31
27		Up	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.281002 ° -122.020570 °		32
28		Up	Erosion / Bank Caving		A		38.281002 ° -122.020570 °		33

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel					Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion					0.75	08/02/2011 08/03/2011	John Williamson

  

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
29		Up	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.281002 ° -122.020570 °		34
30		Up	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.281002 ° -122.020570 °		35
31		Down	Vegetation & Obstructions		A	Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.	38.281002 ° -122.020570 °	Y	36
32		Down	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation present.	38.281002 ° -122.020570 °		37
33		Down	Erosion / Bank Caving		A		38.281002 ° -122.020570 °		38
34		Down	Revetments		A	Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.	38.281002 ° -122.020570 °		39
35		Down	Encroachments		A	Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.	38.281002 ° -122.020570 °		40

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking down stream from N. Texas St. The upstream is underground from the north side of the freeway.

johngw\_c\_20110804\_010.jpg



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream from Camrose Ave.

johngw\_c\_20110804\_011.jpg



Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Camrose Ave.

johngw\_c\_20110804\_012.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream from Dover Ave.

johngw\_c\_20110804\_013.jpg



Levee Mile Report Line	21
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream from Dover Ave.

johngw\_c\_20110804\_014.jpg



Levee Mile Report Line	26
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking upstream from Gulf Dr.

johngw\_c\_20110804\_015.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Channel Inspections**

**Channel Inspection Report By Check Point and View Direction - 2011**

**Fairfield Suisun Sewer District**

Channel	Channel Length	Inspection Start/End	Inspector
Union Avenue Diversion	0.75	08/02/2011 08/03/2011	John Williamson

Levee Mile Report Line	31
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Channels
Item	Vegetation & Obstructions

The photo is looking downstream at Gulf Dr.

johngw\_c\_20110804\_016.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected